

MEMS VOC Gas Sensor

(Model No.:MS-GM5B)

Manual

Version: 2.2

Valid from: 2020.08.25

Taiyuan Tengxing sensor technology Co., Ltd

MS-GM5B MEMS VOC Gas Sensor

Product description

MEMS VOC gas sensor is using MEMS micro-fabrication hot plate on a Si substrate base, gas-sensitive materials used in the clean air with low conductivity metal oxide semiconductor material. When the sensor exposed to gas atmosphere, the conductivity is changing as the detected gas concentration in the air. The higher the concentration of the gas, the higher the conductivity. Use simple circuit can convert the change of conductivity of the gas concentration corresponding to the output signal.



Characters

MEMS technology, strong structure Low power consumption High sensitivity Fast response and resume Simple drive circuit


Application


Gas leak detection for mobile phones, computers and other consumer electronics applications, also for breathing gas detection control, smoke alarm indoor etc.

Main Parameter:


Part No.			MS-GM5B
Sensor Type			MEMS VOC Sensor
Standard Encapsulation			Ceramic
Detection Gas			Ethanol, formaldehyde, toluene &etc.
Detection Range			1~500ppm
Standard Circuit Conditions	Loop Voltage	V _C	≤24V DC
	Heater Voltage	V _H	2.5V±0.1V AC or DC
	Load Resistance	R∟	Adjustable
Sensor character under standard test conditions	Heater Resistance	R _H	$80Ω\pm20Ω$ (room temperature)
	Heater consumption	P _H	≤50mW
	sensitive materials resistance	Rs	1Κ $\Omega\sim$ 30Κ Ω (in 50ppm ethanol)
	Concentration slope	α	≤0.9(R _{200ppm} /R _{500ppm} ethanol)
	Sensitivity	S	R ₀ (in air)/Rs(in 50ppm ethanol)≥3.0
Standard test	Temp. Humidity		20°C±2°C; 55%±5%RH
conditions	Standard test circ	uit	V _H :2.5V±0.1V; V _C :5.0V±0.1V

Sensor Structure Diagram






From bottom.(Unit is mm)




Pin	Connect
1	RH1
2	
3	RH2
4	
5	RS1
6	
7	RS2
8	

Recommend Circuit



Instructions: The above fig is the basic test circuit of M S - G M 5 B . The sensor requires two voltage inputs: heater voltage (V_H) and circuit voltage (V_C). V_H is used to supply specific working temperature to the sensor and it can adopt DC or AC power. V_{out} is the voltage of load resistance R_L which is in series with sensor. Vc supplies the detect voltage to load resistance R_L and it should adopt DC power.

Sensitivity Characteristics:







Fig4.Typical temperature/humidity characteristics


Rs means resistance of sensor in 50ppm alcohol gas under

different temp. and humidity. Rso means resistance of the

Fig3.Typical Sensitivity Curve

Rs means resistance in target gas with different concentration, R_0 means resistance of sensor in clean air.








Fig5.Responce and Resume

The output in above Fig is the voltage of RL which is in series with sensor. All tests are finished under standard test conditions and the test gas is 50ppm acohol gas.

Fig6. Linearity character

The output in above Fig is the voltage of RL which is in series with sensor. All tests are finished under standard test conditions.

Long-term stability




Fig7.long-term Stability

Test is finished in standard test conditions, the abscissa is observing time and the ordinate is voltage output of RL.

Instructions:

1. Preheating time

Sensor's resistance may drift reversibly after long-term storage without power. It need to preheat the sensor to reach inside chemical equilibrium. Preheating voltage is same with heating voltage V_H . The suggested preheating time as follow:

Storage Time	Suggested aging time
Less than one month	No less than 24 hours
1 ~ 6 months	No less than 48 hours
More than six months	No less than 72 hours

2. Calibration

Sensor's accuracy is effected by many factors such as reference resistance's difference, the sensitivity difference, temperature, humidity, interfering gases, preheating time, the relationship between input and output is not linear, hysteretic and non-repetitive. For absolute concentration measurement, they need regular calibration (one-point calibration / multi-points calibration for full scale) to ensure that the measuring value is accurate. For relative measurement calibration is not required.

Cautions

1. Following conditions must be prohibited

1.1 Exposed to organic silicon steam

Sensing material will lose sensitivity and never recover if the sensor absorbs organic silicon steam. Sensors must be avoid exposing to silicon bond, fixature, silicon latex, putty or plastic contain silicon environment.

1.2 High Corrosive gas

If the sensors are exposed to high concentration corrosive gas (such as H2S, SOX, Cl2, HCL etc.), it will not only result in corrosion of sensors structure, also it causes sincere sensitivity attenuation.

1.3 Alkali, Alkali metals salt, halogen pollution

The sensors performance will be changed badly if sensors be sprayed polluted by alkali metals salt especially brine, or be exposed to halogen such as fluorine.

1.4 Touch water

Sensitivity of the sensors will be reduced when spattered or dipped in water.

1.5 Freezing

Do avoid icing on sensor's surface, otherwise sensing material will be broken and lost sensitivity.

1.6 Applied voltage

Applied voltage on sensor should not be higher than 120mW, it will cause irreversible heater damaged, also hurt from static, so anti-static precautions should be taken when touching sensors.

2. Following conditions should be avoided

2.1 Water Condensation

Indoor conditions, slight water condensation will influence sensors' performance lightly. However, if water condensation on sensors surface and keep a certain period, sensors' sensitive will be decreased.

2.2 Used in high gas concentration

No matter the sensor is electrified or not, if it is placed in high gas concentration for long time, sensors characteristic will be affected. If lighter gas sprays the sensor, it will cause extremely damage.

2.3 Long time exposed to extreme environment

No matter the sensors electrified or not, if exposed to adverse environment for long time, such as high humidity, high temperature, or high pollution etc., it will influence the sensors' performance badly.

2.4 Vibration

Continual vibration will result in sensors down-lead response then break. In transportation or assembling line, pneumatic screwdriver/ultrasonic welding machine can lead this vibration.

2.5 Concussion

If sensors meet strong concussion, it may lead its lead wire disconnected.

2.6 Soldering

2.6.1Recommended conditions for reflow soldering

neutral atmosphere

soldering temperature $250 \pm 10^{\circ}$ C

avoid flux steam

2.6.2Recommended conditions for manually soldering

rosin flux with least chlorine

soldering temperature ≤350°C

lasting time $\leq 5s$.

If disobey the above using terms, sensors sensitivity will be reduced.

Package

The surface of the MEMS sensor is affixed with a special protective film to prevent the influence of dust, water, atmosphere and high temperature. After the welding is completed, the protective film can be removed.

